



NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://emnr.state.nm.us/ocd/District/III/3district.htm>

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 6 May 2009 Operator Lively Exp. API #30-0 95-21418
Property Name Lively Well No. 20 Location: Unit P Section 12 Township 26N Range 8W
Well Status (Shut-In or Producing) Initial PSI: Tubing 147 Intermediate NA Casing 363 Bradenhead 717m

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	Bradenhead	INTERM			
	BH	Int	Csg	Int	Csg
5 min	<u>0</u>	<u>1A</u>	<u>363</u>	<u>NA</u>	<u>363</u>
10 min	<u>0</u>	<u>NA</u>	<u>363</u>	<u>NA</u>	<u>363</u>
15 min	<u>0</u>	<u>NA</u>	<u>363</u>	<u>NA</u>	<u>363</u>
20 min					
25 min					
30 min					

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing	<u>X</u>	
Nothing		
Gas		
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE NA

REMARKS:

BH 1700 Small PRESS TREN WORKING FOR REMEDIATION TEST

By [Signature]

Witness _____

(Position)

E-mail address _____

