



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 6 May 2009 Operator Lively Exp. API #30-0 95-23969

Property Name Lively Well No. 19E Location: Unit N Section 12 Township 26N Range 8W

Well Status (Shut-In or Producing) Initial PSI: Tubing 157 Intermediate N/A Casing 221 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	BH	Bradenhead		INTERM	
		Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>	<u>N/A</u>	<u>221</u>	<u>N/A</u>	<u>229</u>
10 min	<u>0</u>	<u>N/A</u>	<u>223</u>	<u>N/A</u>	<u>229</u>
15 min	<u>0</u>	<u>N/A</u>	<u>227</u>	<u>N/A</u>	<u>230</u>
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing	
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE N/A

REMARKS:

By [Signature]

Witness _____

(Position)

E-mail address _____

