



NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3distr.htm](http://emnr.state.nm.us/ocd/District%20III/3distr.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 1 May 2009 Operator Lively Exp. API #30-0 95-23969

Property Name Lively Well No. 2E Location: Unit H Section 21 Township 28N Range 8W

Well Status (Shut-In or Producing) Initial PSI: Tubing 129 Intermediate 530 Casing 129 Bradenhead 30

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE					
	Bradenhead			INTERM		
	BH	Int	Csg	Int	Csg	
5 min	<u>127m</u>	<u>520</u>	<u>141</u>	<u>127m</u>	<u>144</u>	
10 min	<u>127m</u>	<u>525</u>	<u>141</u>	<u>127m</u>	<u>144</u>	
15 min	<u>127m</u>	<u>525</u>	<u>141</u>	<u>127m</u>	<u>144</u>	
20 min						
25 min						
30 min						

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		<u>X</u> <u>Light Bleed</u>
Surges		
Down to Nothing	<u>X</u>	
Nothing		
Gas	<u>X</u>	<u>X</u>
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR ☐ FRESH ☐ SALTY ☐ SULFUR ☐ BLACK ☐

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE 127m

REMARKS:

Bleed Down After 3 min to Light Bleed

By [Signature]
[Signature]
(Position)

Witness _____

E-mail address _____

