



NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3distric.htm](http://emnrd.state.nm.us/ocd/District%20III/3distric.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 5-21-09 Operator Burlingtrude API #30-0 45-07284
Property Name Flourence C Well No. 2 Location: Unit Section 20 Township 28 Range 8
Well Status (Shut-In or Producing) Initial PSI: Tubing 123 Intermediate 30 Casing 137 Bradenhead 13

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
TIME					
5 min		30			141
10 min		30			141
15 min		30			141
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	✓
Down to Nothing	✓
Nothing	
Gas	DIST. 3
Gas & Water	✓
Water	OIL CONS. DIV.

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 7

INTERMEDIATE 0

RCVD MAY 21 '09

REMARKS:

BH had a puff when opened - then flowed with surges at 43 seconds - flowed w/ surges whole 15 minutes - Intermediate blew for 1.5 min.

By Ma. J. J.
(Position)

Witness Monica Kunkling

E-mail address

Plunger dropped in 7.5 min into bti