

NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division
Aztec District Office
1000 Rio Brazos Road
Aztec, NM 87410
(505)334-6178 FAX:(505)334-6170

<http://emnr.state.nm.us/ocd/DistrictIII/3district.htm>

BRADENHEAD TEST REPORT

(Submit 1 copy to above address)

Date of Test 5-21-09 Operator Dugan Production Corp. API # 30-045-23847
Property Name DOME NAVAJO 21-27-13 Well No 3 Location: Unit M Section 21 Township 27N Range 13W
Well Status(Shut-In or Producing) Initial PSI. 15 Intermediate N/A Casing 22 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

TIME	Bradenhead			Interm		
	BH	Int	Csg	Int	Csg	
5 minutes	0		22			
10 minutes	0		22			
15 minutes	0		22			
20 minutes						
25 minutes						
30 minutes						

Steady Flow

Surges

Down to Nothing

Nothing

Gas

Gas & Water

Water

FLOW CHARACTERISTICS

BRADENHEAD

INTERMEDIATE

NOTHING	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN

BRADENHEAD

0

INTERMEDIATE

REMARKS:

By Chris O'Neil #97 Switcher
(Position)

Witness _____

