

NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division

Aztec District Office

1000 Rio Brazos Road

Aztec, NM 87410

(505)334-6178 FAX (505)334-6179

<http://enrdd.state.nm.us/ocd/District3.htm>

BRADENHEAD TEST REPORT

(Submit 1 copy to above address)

Date of Test 5-13-09 Operator Dugan Production Corp. API # 30-045-25866
Property Name MONTE CARLO Well No 1 Location: Unit K Section 7 Township 30N Range 14W
Well Status (Shut-In or Producing) Initial PSI: Tubing 0 Intermediate 0 Casing 0 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

FLOW CHARACTERISTICS

TIME	Bradenhead			Interm		
	BH	Int	Csg	Int	Csg	
5 minutes	0		0			
10 minutes	0		0			
15 minutes	0		0			
20 minutes	0		0			
25 minutes						
30 minutes						

Steady Flow

Surges

Down to Nothing

Nothing

Gas

Gas & Water

Water

BRADENHEAD

INTERMEDIATE

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN

BRADENHEAD

0

INTERMEDIATE

REMARKS:

Braden head had no pressure

By

Kamie Stufflebeam

Witness

Switcher

(Position)

