

NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT.

Oil Conservation Division
Aztec District Office
1000 Rio Brazos Road
Aztec, NM 87410
(505)334-6178 FAX:(505)334-6170

<http://emnr.state.nm.us/ocd/District/III/3ddistrict.htm>

BRADENHEAD TEST REPORT

(Submit 1 copy to above address)

Date of Test 5-12-09 Operator Dugan Production Corp. API # 30-045-26077
Property Name MONTE CARLO Well No. 2 Location: Unit M Section 24 Township 30N Range 15W
Well Status(Shut-In or Producing) Initial PSI: Tubing 1000 Intermediate _____ Casing 550 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURE					FLOW CHARACTERISTICS	
	Bradenhead		Interm			BRADENHEAD	INTERMEDIATE
	BH	Int	Csg	Int	Csg		
5 minutes	0		550			Steady Flow	
10 minutes	0		550			Surges	
15 minutes	0		550			Down to Nothing	
20 minutes	0		550			Nothing	✓
25 minutes						Gas	
30 minutes						Gas & Water	
						Water	1

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN BRADENHEAD 0 INTERMEDIATE _____

REMARKS:

No pressure on bradenhead

By Kamie Stufflebeam Witness _____
Switcher
(Position)

