

NEW MEXICO ENERGY, MINERALS  
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division  
Aztec District Office  
1000 Rio Brazos Road  
Aztec, NM 87410  
(505)334-6178 FAX: (505)334-6170

[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

**BRADENHEAD TEST REPORT**

(Submit 1 copy to above address)

Date of Test 05-19-09 Operator Dugan Production Corp. API # 30-045-31694  
Property Name MARY LOU Well No 91 Location: Unit H Section 32 Township 24N Range 10W  
Well Status (Shut-In or Producing) Initial PSI: Tubing 28 Intermediate      Casing 56 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

TIME	Bradenhead			Interm		
	BH	Int	Csg	Int	Csg	
5 minutes	0		56			
10 minutes	0		56			
15 minutes	0		56			
20 minutes	0		56			
25 minutes						
30 minutes						

Steady Flow

Surges

Down to Nothing

Nothing

Gas

Gas & Water

Water

FLOW CHARACTERISTICS

BRADENHEAD INTERMEDIATE

BRADENHEAD	INTERMEDIATE
<u>Nothing</u>	

**If bradenhead flowed water, check all of the descriptions that apply below:**

CLEAR      FRESH      SALTY      SULFUR      BLACK     

**5 MINUTE SHUT-IN**

BRADENHEAD

10

INTERMEDIATE

REMARKS:

By

[Signature]  
Switcher  
(Position)

Witness

