

NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division
Aztec District Office
1000 Rio Brazos Road
Aztec, NM 87410
(505)334-6178 FAX:(505)334-6170

<http://emrnr.state.nm.us/ocd/District/III/3distnc.htm>

BRADENHEAD TEST REPORT

(Submit 1 copy to above address)

Date of Test 5-13-09 Operator Dugan Production Corp. API # 30-045-31945
Property Name MONTE CARLO COM Well No 90 Location: Unit M Section 7 Township 30N Range 14W
Well Status(Shut-In or Producing) Initial PSI: Tubing 50 Intermediate _____ Casing 15 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

TIME	Bradenhead			Interm		
	BH	Int	Csg	Int	Csg	
5 minutes	0		15			
10 minutes	0		15			
15 minutes	0		15			
20 minutes	0		15			
25 minutes						
30 minutes						

FLOW CHARACTERISTICS

Steady Flow
Surges
Down to Nothing
Nothing
Gas
Gas & Water
Water

BRADENHEAD	INTERMEDIATE

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN BRADENHEAD 0 INTERMEDIATE _____

REMARKS:

No pressure on bradenhead

By

Kamie Stiffbeam

Switcher

(Position)

Witness _____

