

NEW MEXICO ENERGY, MINERALS  
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division  
Aztec District Office  
1000 Rio Brazos Road  
Aztec, NM 87410  
(505)334-6178 FAX:(505)334-6170

<http://emnr.state.nm.us/ocd/DistrictIII/3distinc.htm>

**BRADENHEAD TEST REPORT**

(Submit 1 copy to above address)

Date of Test 5-13-09 Operator Dugan Production Corp. API # 30-045-31956  
Property Name NICE COM Well No. 90 Location: Unit O Section 7 Township 30N Range 14W  
Well Status(Shut-In or Producing) Initial PSI: Tubing 105 Intermediate \_\_\_\_\_ Casing 14 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

TIME	Bradenhead			Interm		
	BH	Int	Csg	Int	Csg	
5 minutes	0		14			
10 minutes	0		14			
15 minutes	0		14			
20 minutes	0		14			
25 minutes						
30 minutes						

FLOW CHARACTERISTICS

Steady Flow

Surges

Down to Nothing

Nothing

Gas

Gas & Water

Water

BRADENHEAD	INTERMEDIATE

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR \_\_\_\_\_ FRESH \_\_\_\_\_ SALTY \_\_\_\_\_ SULFUR \_\_\_\_\_ BLACK \_\_\_\_\_

5 MINUTE SHUT-IN

BRADENHEAD 0 INTERMEDIATE \_\_\_\_\_

REMARKS:

No pressure on bradenhead

By

Lamie Guffelbean

Witness

Switcher

(Position)

