

NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division
Aztec District Office
1000 Rio Brazos Road
Aztec, NM 87410
(505)334-6178 FAX:(505)334-6170

<http://emnr.state.nm.us/ocd/District/III/3distinc.htm>

BRADENHEAD TEST REPORT

(Submit 1 copy to above address)

Date of Test 5-19-9 Operator Dugan Production Corp. API # 30-045-32987
Property Name KINGFISH COM Well No 90S Location: Unit F Section 3 Township 26N Range 13W
Well Status (Shut-In or Producing) Initial PSI: Tubing 38 Intermediate n/a Casing 0 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

FLOW CHARACTERISTICS

TIME	Bradenhead			Interm				FLOW CHARACTERISTICS	
	BH	Int.	Csg	Int	Csg			BRADENHEAD	INTERMEDIATE
5 minutes	0		0				Steady Flow		
10 minutes	0		0				Surges		
15 minutes	0		0				Down to Nothing		
20 minutes							Nothing	nothing	
25 minutes							Gas		
30 minutes							Gas & Water		
							Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN

BRADENHEAD

INTERMEDIATE

REMARKS:

By _____ Witness _____

Switcher

(Position)

