

NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division
Aztec District Office
1000 Rio Brazos Road
Aztec, NM 87410
(505)334-6178 FAX:(505)334-6170

<http://emrmd.state.nm.us/ocd/District/III/3distnc.htm>

BRADENHEAD TEST REPORT

(Submit 1 copy to above address)

Date of Test 05-19-09 Operator Dugan Production Corp. API # 30-045-34216
Property Name CALGARY Well No 91 Location: Unit N Section 6 Township 23N Range 10W
Well Status (Shut-In or Producing) Initial PSI: Tubing 100 Intermediate NA Casing 54 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

TIME	Bradenhead		Interm	
	BH	Int	Csg	Int
5 minutes	0		54	
10 minutes	0		54	
15 minutes	0		54	
20 minutes	0		54	
25 minutes				
30 minutes				

Steady Flow

Surges

Down to Nothing

Nothing

Gas

Gas & Water

Water

FLOW CHARACTERISTICS

BRADENHEAD

INTERMEDIATE

<u>Nothing</u>	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN

BRADENHEAD

0

INTERMEDIATE

REMARKS:

By _____ Witness _____

Switcher

(Position)

