

NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division
Aztec District Office
1000 Rio Brazos Road
Aztec, NM 87410
(505)334-6178 FAX:(505)334-6170

<http://emnr.state.nm.us/ocd/District/III/3district.htm>

BRADENHEAD TEST REPORT

(Submit 1 copy to above address)

Date of Test 5-20-09 Operator Dugan Production Corp. API # 30-045-05684
Property Name WEST BISTI UNIT Well No 127 Location: Unit G Section 28 Township 26N Range 13W
Well Status(Shut-In or Producing) Initial PSI: Tubing 8304AS Intermediate Casing 0 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURE						FLOW CHARACTERISTICS	
	Bradenhead			Interm			BRADENHEAD	INTERMEDIATE
	BH	Int	Csg	Int	Csg			
5 minutes	0		0					Steady Flow
10 minutes	0		0					Surges
15 minutes	0		0					Down to Nothing
20 minutes	0		0					Nothing
25 minutes								Gas
30 minutes								Gas & Water
								Water

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN

BRADENHEAD 0

INTERMEDIATE

REMARKS:

By Ron Hanel 54 Witness _____
Switcher
(Position)

