

NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division
Aztec District Office
1000 Rio Brazos Road
Aztec, NM 87410
(505)334-6178 FAX:(505)334-6170

<http://emnr.state.nm.us/ocd/District/III/3distnc.htm>

BRADENHEAD TEST REPORT

(Submit 1 copy to above address)

Date of Test 5-21-09 Operator Dugan Production Corp. API # 30-045-05710
Property Name WEST BISTI UNIT Well No 124 Location: Unit A Section 28 Township 26N Range 13W
Well Status (Shut-In or Producing) Initial PSI: Tubing 100 Intermediate N/A Casing SSO Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

FLOW CHARACTERISTICS

TIME	Bradenhead			Interm				FLOW CHARACTERISTICS	
	BH	Int	Csg	Int	Csg			BRADENHEAD	INTERMEDIATE
5 minutes	0		SSO				Steady Flow		
10 minutes	0		SSO				Surges		
15 minutes	0		SSO				Down to Nothing		
20 minutes	0		SSO				Nothing	X	
25 minutes	0		SSO				Gas		
30 minutes	0		SSO				Gas & Water		
							Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN BRADENHEAD 0 INTERMEDIATE _____

REMARKS:

By

Travis Brewton #38
Switcher
(Position)

Witness _____

