## NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

Oil Conservation Division
Aztec District Office
1000 Rio Brazos Road
Aztec, NM 87410
(505)334-6178 FAX:(505)334-6170

http://emnrd.state.nm.us/ocd/District III/3distric.htm

## **BRADENHEAD TEST REPORT**

(Submit 1 copy to above address)

Date of Test	05/19/	<u>05/19/09</u> Operator			Dugan I	AP	ગ #	30-045-26945						
Property Name	e <u> </u>	CHAMP			Well No 4 Location		Location: \	: Unit <u>G</u>		Section	5	_Township		nge <u>10W</u>
Well Status(Shut-In)or Producing)			) Initial	PSI:	Tubing 💍 💍		Intermedia	te		Casing	12		Bradenhead 6	
OPĖN BRA		PRESS	SURE	RME	DIATE T	О АТМО	OSPHERE			Y FOR			EAĊH	
TIME	BH Int		Interm	Cen						NHEAD			DIATE	
5 mintues	0	12		Cog		Steady Flo	-		MDL	MILAD		INTERNIE	DIATE	
	0	12			İ		_						<u></u>	
10 minutes	0	<u> </u>		-		Surges	_				<del></del>		· · ·	
15 minutes		12			İ _	Down to N	-					,····		
20 minutes	h					Nothing	-	Noth	Uching			<u>-</u>		
25 minutes	\ <u>-</u>		-		(	Gas	-				<del></del>			
30 minutes			-	Gas & Water							<del></del>			
				Water								. , >.		
<u>If bradenh</u>	nead flo	wed v	vat <u>er,</u>	chec	k all of	the de	scription	s that a	pply	/ below	<u>/:</u>			
		CLEAF	₹		FRESH _		SALTY _	SU	JLFUI	R	BLAC	K	_	
5 MINUTÈ SHUT-IN BRADENHE REMARKS:			ENHEA	AD			INTERMEDIATE				- 6789	10111273 A ECEIVE FUN 2005 CONS. DIV. DIS	14 16 TO	
			<del></del>		<u>:</u>	<u> </u>					<u></u>	2345 B	ECFIVE	D 318
					<u> </u>							OIL	CONS. DIV. DIS	7.3 22
				•							,		12526272	
Ву		Parist	5-14	5//2a	m		,	Witness					(2526272)	
•			Switc				<u> </u>							
			(Positio											