

NEW MEXICO ENERGY, MINERALS  
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division  
Aztec District Office  
1000 Rio Brazos Road  
Aztec, NM 87410  
(505)334-6178 FAX:(505)334-6170

<http://emnr.state.nm.us/ocd/District/III/3distric.htm>

**BRADENHEAD TEST REPORT**

(Submit 1 copy to above address)

Date of Test 5-20-09 Operator Dugan Production Corp. API # 30-045-29433  
Property Name DOMA NAVAJO 12 26 13 Well No. 90 Location: Unit K Section 12 Township 26N Range 13W  
Well Status(Shut-In or Producing) Producing Initial PSI: Tubing 5 Intermediate          Casing 6 Bradenhead 1

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE						FLOW CHARACTERISTICS	
TIME	Bradenhead			Interm		BRADENHEAD	INTERMEDIATE
	BH	Int	Csg	Int	Csg		
5 minutes	0		6			Steady Flow	
10 minutes	0		6			Surges	
15 minutes	0		6			Down to Nothing	
20 minutes						Nothing	
25 minutes						Gas	
30 minutes						Gas & Water	
						Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR \_\_\_\_\_ FRESH \_\_\_\_\_ SALTY \_\_\_\_\_ SULFUR \_\_\_\_\_ BLACK \_\_\_\_\_

5 MINUTE SHUT-IN BRADENHEAD 0 INTERMEDIATE \_\_\_\_\_

REMARKS



By [Signature] Switcher  
(Position) Witness \_\_\_\_\_