

NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division
Aztec District Office
1000 Rio Brazos Road
Aztec, NM 87410
(505)334-6178 FAX:(505)334-6170

<http://emnr.state.nm.us/ocd/District/III/3distinc.htm>

BRADENHEAD TEST REPORT

(Submit 1 copy to above address)

Date of Test 5-12-09 Operator Dugan Production Corp. API # 30-045-30921
Property Name HUMBLE KIRTLAND Well No 90 Location: Unit B Section 13 Township 30N Range 14W
Well Status (Shut-In or Producing) Initial PSI: 95 Intermediate Casing 8 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

TIME	Bradenhead			Interm		
	BH	Int	Csg	Int	Csg	
5 minutes	0		8			
10 minutes	0		8			
15 minutes	0		8			
20 minutes	0		8			
25 minutes						
30 minutes						

Steady Flow
Surges
Down to Nothing
Nothing
Gas
Gas & Water
Water

FLOW CHARACTERISTICS

BRADENHEAD	INTERMEDIATE
✓	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN BRADENHEAD 0 INTERMEDIATE

REMARKS:

By Roslyn Vaden
Switcher
(Position)

Witness

