## NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

Oil Conservation Division
Aztec District Office
1000 Rio Brazos Road
Aztec, NM 87410
(505)334-6178 FAX:(505)334-6170

http://emnrd.state.nm.us/ocd/District III/3distric.htm

## **BRADENHEAD TEST REPORT**

(Submit 1 copy to above address)

	I									
Date of Test <u>05-20-09</u> Operator			Dugan Production Corp.			API #	30-045-34053			
Property Name	PHOÉBE	COM	_Well No _	90	_Location: Un	it <u>D</u>	_Section _	22 Township	24N Rang	je <u>10W</u>
Well Status(Shเ	ut-In or Producing)	Initial PSI:	Tubing _	110	_Intermediate		_Casing _	.55	_Bradenh <u>ead</u>	0.
TIME 5 mintues 10 minutes 15 minutes 20 minutes 25 minutes 30 minutes	DENHEAD AND PRESSUB Fradenhead  BH Int Csg  D S5  D S5	JRE Interm		Steady Flow Surges Down to Not Nothing Gas Gas & Wate	thing	FLOW	CHARACT	15 MINUTES  TERISTICS  INTERME		
lf brädenh	ead flowed w	ater, che		Water <b>f the des</b>	scriptions	that appl	y below	<u>/:</u>		
	CLEAR	<u>-</u>	FRESH_		_SALTY	SULFU	JR	BLACK	_	
5 MINUTE S	HUT-IN	BRADENHE.	AD _			TERMEDIATI	E	·		
	* C					-			12131415	
Ву	Arch	Switcher (Position)	lle	~₺	Wi	tness		100 HE OF OF OF OF	CEIVED JUN 2009 JONS. DIV. DIST. 3	11/18/19202122