

NEW MEXICO ENERGY, MINERALS  
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division  
Aztec District Office  
1000 Rio Brazos Road  
Aztec, NM 87410  
(505)334-6178 FAX: (505)334-6170

<http://emnr.state.nm.us/ocd/District/III/3distnc.htm>

**BRADENHEAD TEST REPORT**

(Submit 1 copy to above address)

Date of Test 5/13/09 Operator Dugan Production Corp. API # 30-045-05601  
Property Name NICKSON Well No. 2 Location: Unit O Section 35 Township 26N Range 8W  
Well Status (Shut-In or Producing) Initial PSI: Tubing 60 Intermediate            Casing 85 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

TIME	Bradenhead			Interm		
	BH	Int	Csg	Int	Csg	
5 minutes	0		85			
10 minutes						
15 minutes	0		85			
20 minutes						
25 minutes	0		85			
30 minutes						

FLOW CHARACTERISTICS

Steady Flow  
Surges  
Down to Nothing  
Nothing  
Gas  
Gas & Water  
Water

BRADENHEAD	INTERMEDIATE
X	


**If bradenhead flowed water, check all of the descriptions that apply below:**

CLEAR            FRESH            SALTY            SULFUR            BLACK           

**5 MINUTE SHUT-IN** BRADENHEAD 0 INTERMEDIATE           

REMARKS:

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

By   
Switcher  
(Position)

Witness \_\_\_\_\_

