

NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division
Aztec District Office
1000 Rio Brazos Road
Aztec, NM 87410
(505)334-6178 FAX:(505)334-6170

[http://emnr.state.nm.us/ocd/District III/3d/district.htm](http://emnr.state.nm.us/ocd/District%20III/3d/district.htm)

BRADENHEAD TEST REPORT

(Submit 1 copy to above address)

Date of Test 5-12-09 Operator Dugan Production Corp. API # 30-045-10776
Property Name CUCCIA Well No. 1 Location: Unit G Section 14 Township 31N Range 13W
Well Status(Shut-In or Producing) Initial PSI: Tubing 310 Intermediate Casing 720 Bradenhead 7

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

FLOW CHARACTERISTICS

TIME	Bradenhead			Interm				FLOW CHARACTERISTICS	
	BH	Int	Csg	Int	Csg			BRADENHEAD	INTERMEDIATE
5 minutes	0		720				Steady Flow		
10 minutes	0		720				Surges		
15 minutes	0		720				Down to Nothing	✓	
20 minutes	0		720				Nothing		
25 minutes							Gas		
30 minutes							Gas & Water		
							Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN BRADENHEAD 0 INTERMEDIATE

REMARKS:

No Build up Pres.

By Chad Boggs #78 Witness
Switcher
(Position)

