



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

MECHANICAL INTEGRITY TEST REPORT

(TA OR UIC)

Date of Test 6-24-09 Operator Emugen Res. API # 30-0 39-24454

Property Name Quintana Mesa Well # 100 Location: Unit Sec 28 Twn 32 Rge 5

Land Type:

State
Federal
Private
Indian

Well Type:

Water Injection
Salt Water Disposal
Gas Injection
Producing Oil/Gas
Pressure observation

Temporarily Abandoned Well (Y/N): TA Expires: 6/24/2014

Casing Pres. 0 Tbg. SI Pres. Max. Inj. Pres.
Bradenhead Pres. 0 Tbg. Inj. Pres.
Tubing Pres. 1221
Int. Casing Pres. N/A

Pressured annulus up to 620 psi. for 30 mins. Test passed/failed

REMARKS:

Packer set at 3759

dropped to 601

RCVD JUN 24 '09

OIL CONS. DIV


DIST. 3

By [Signature]
(Operator Representative)

Witness [Signature]
(NMOCD)

Consultant
(Position)

Revised 02-11-02



Emergen Res.

CHART NO. MC MP-1000-IHR

Quintana Roo #100

METER

TAKEN OFF

CHART PUT ON

M 28-32-5

LOCATION

REMARKS

30-039-24450

RDV JUN 24/09

01 CONS. DIV

M. M. ...