



NEW MEXICO ENERGY, MINERALS  
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE  
1000 RIO BRAZOS ROAD  
AZTEC NM 87410  
(505) 334-6178 FAX: (505) 334-6170  
[http://emrdr.state.nm.us/ocd/District III3distric.htm](http://emrdr.state.nm.us/ocd/District%20III3distric.htm)

BRADENHEAD TEST REPORT


(submit 1 copy to above address)

Date of Test 6-24-09 Operator Caneco API #30-0 45-23817  
Property Name Grumbling A Well No. 2A Location: Unit P Section 22 Township 28 Range 8  
Well Status (Shut-In or Producing) Initial PSI: Tubing 180 Intermediate NA Casing 199 Bradenhead 3

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

| Testing | PRESSURE   |                |            | INTERM |     |
|---------|------------|----------------|------------|--------|-----|
|         | BH         | Bradenhead Int | Csg        | Int    | Csg |
| TIME    |            |                |            |        |     |
| 5 min   | <u>1</u>   |                | <u>199</u> |        |     |
| 10 min  | <u>1.4</u> |                | <u>199</u> |        |     |
| 15 min  | <u>1.6</u> |                | <u>199</u> |        |     |
| 20 min  | <u>1.8</u> |                | <u>199</u> |        |     |
| 25 min  |            |                |            |        |     |
| 30 min  |            |                |            |        |     |

|                 | BRADENHEAD                                       | INTERMEDIATE |
|-----------------|--------------------------------------------------|--------------|
| Steady Flow     | <input checked="" type="checkbox"/>              |              |
| Surges          |                                                  |              |
| Down to Nothing |                                                  |              |
| Nothing         |                                                  |              |
| Gas             |                                                  |              |
| Gas & Water     |                                                  |              |
| Water           | <u>clear</u> <input checked="" type="checkbox"/> |              |



If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR ☒ FRESH \_\_\_\_\_ SALTY \_\_\_\_\_ SULFUR \_\_\_\_\_ BLACK \_\_\_\_\_

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 1.2 INTERMEDIATE \_\_\_\_\_

REMARKS:

BH 1" valve with flow line going to above ground tank,  
Water on BH w/ not enough pressure to get down  
line to tank. Sample taken

By Greg Daltroy  
MSO  
(Position)

Witness Richard L. Jones

E-mail address \_\_\_\_\_