

NEW MEXICO ENERGY, MINERALS  
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division  
Aztec District Office  
1000 Rio Brazos Road  
Aztec, NM 87410  
(505)334-6178 FAX:(505)334-6170

[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

**BRADENHEAD TEST REPORT**

(Submit 1 copy to above address)

Date of Test 5-20-09 Operator Dugan Production Corp. API # 30-045-05642  
Property Name WEST BISTI UNIT Well No 144 Location: Unit D Section 34 Township 26N Range 13W  
Well Status(Shut-In or Producing) Initial PSI: Tubing 845 LBS Intermediate \_\_\_\_\_ Casing 0 Bradenhead 24 LBS

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

TIME	Bradenhead			Interm		
	BH	Int	Csg	Int	Csg	
5 minutes	0		0			
10 minutes	0		0			
15 minutes	0		0			
20 minutes	0		0			
25 minutes						
30 minutes						

Steady Flow

Surges

Down to Nothing

Nothing

Gas

Gas & Water

Water

FLOW CHARACTERISTICS

BRADENHEAD

INTERMEDIATE

BRADENHEAD	INTERMEDIATE
✓	
✓	

**If bradenhead flowed water, check all of the descriptions that apply below:**

CLEAR \_\_\_\_\_ FRESH \_\_\_\_\_ SALTY \_\_\_\_\_ SULFUR \_\_\_\_\_ BLACK \_\_\_\_\_

**5 MINUTE SHUT-IN**

BRADENHEAD 2 LBS

INTERMEDIATE \_\_\_\_\_

REMARKS:

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

By Ron Hamed 54  
\_\_\_\_\_  
Switcher  
(Position)

Witness \_\_\_\_\_

