٠.	Sù	bmit	hv	Email	1
•	ำวน	MILLIE	vγ	THE STATE OF	

Print Form ...

NEW MEXICO ENERGY, MINERALS AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION

AZTEC DISTRICT OFFICE 1000 RIO BRAZOS ROAD AZTEC, NM 87410 (505 334-6178 FAX (505) 334-6170 http://www.emnrd.state.nm.us/ocd/

BRADENHEAD TEST

-	· · · · · · · · · · · · · · · · · · ·	.,,	i				gymns/ Charles						
Date of Test	5/10/2009		Operator	Chaparral Oil 8	& Gas	A	PI # 30-045-2	20611					
Property Name	34.7 "	and Number)	Locatio	on: Unit	Section	n 24 Township 28N	Range 11W]					
Well Status: Shut-in or Producing Producing													
Pressures: Tubing 3 Intermediate na Casing 15 Bradenhead 0													
OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH													
	Bradenhead PSIs		s	Intermediate			Bradenhead Intermediate						
<u>Time</u>		Casing Monitor N	INT Monitor	Intermediate Blowdown									
5 minutes 10 minutes 15 minutes 20 minutes 25 minutes 30 minutes	0 115 0 115 0 115 0 115	5 NA 5 NA		NA NA NA NA		Steady Flow Surges Down to Nothing No Flow Gas Gas and Water Water							
If bradenhead flowed water, check all of the descriptions that apply below: Clear Fresh Salty Sulfur Black													
5 Minute Shut-in Bradenhead 0 Intermediate Ina RECEIVED 8													
REMARKS:							C. 6181 (19)	S. DIV. DIST. 3					
By: Harley Cho	ettinger					Witness:							
(Position)													