NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

Oil Conservation Division

Aztec District Office

1000 Rio Brazos Road

Aztec, NM 87410

(505)334-6178 FAX:(505)334-6170

http://emnrd.state.nm.us/ocd/District III/3distric.htm

BRADENHEAD TEST REPORT

(Submit 1 copy to above address)

Date of Test	est <u>5-/9-09</u> Operator		Dugan Production Corp.			API #	30-045-25835				
Property Name	BISTI ST	ATE COM	_Well No	1	_Location: Unit	M	Section	2	Township	25N R	ange <u>13V</u>
Well Status(Sh	ut-In or Froducin	g) Initial PSI:	Tubing	41BS	Intermediate		_Casing	7	LBS.	_Bradenh <u>ea</u>	ad 702
OPEN BRA		SSURE Interm		TO ATMO	SPHERE INDI	FLOW	LY FOR CHARAC				
	θ 7	lint Osg	٦	Stoody Floy		DIVAD	LIVILAD		HALEKWIE	DIATE	
5 mintues 10 minutes	0 7		†	Steady Flow Surges							
15 minutes	0 7		1	Down to No	thing ——				*		
20 minutes	0 7		1	Nothing		<i>y</i>			· · · · · · · · · · · · · · · · · · ·		
25 minutes	0 7			Gas	.	<u> </u>					
30 minutes	0 7			Gas & Wate							•
	•	•		Water		,					
<u>if bradenh</u>	ead flowed	water, che	ck all d	of the des	scriptions th	at appl	y belov	<u>v:</u>			•
	CLEA	.R	_FRESH	10	SALTY	SULFU	JR	BLA	CK	_	
5 MINUTE S	SHUT-IN	BRADENHE	AD	51BS.	_ INTER	RMEDIAT	E		1891011	12737478	
REMARKS.									A REC	EIVED	611 18 15
	•							\ <u>;</u>	V OIL CON	N 2009	2027
	-	<u> </u>		-		•			20 65 85 V		
					, <u>, , , , , , , , , , , , , , , , , , </u>		. *****		05	<u> </u>	'
Ву	By Continual o				54 With						
•		Switcher (Position)			_						