Submit by Email* Print Form
-----------------------------

## NEW MEXICO ENERGY, MINERALS AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION

AZTEC DISTRICT ÔFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505 334-6178 FAX (505) 334-6170
http://www.emnrd.state.nm.us/ocd/

## **BRADENHEAD TEST**

		,	France	Horse				
Date of Test	05/25/09	Operator _	may Bruces		A	PI#	30-045-23838	
Property Nam	e cowsaround 22-2 (Well Name and Number)	Location:	Unit b	Section 2	2 Township 26n		e 12w WD JUL 7'09	
Well Status: S	hut-in or Producing pro	oducing				Ol	L CONS. DIV. DIST. 3	
Pressures:	Tubing 9 Inter	mediate na	Casing <sup>3</sup>	В	radenhead 0			
OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH								
	Bradenhead PS	ls	Intermed	ate		Drade	enhead Intermediate	
<u>Time</u>	BH Casing Blowdown Monitor I			Casing Monitor		Diaue	imeau imermediate	
5 minutes 10 minutes 15 minutes 20 minutes 25 minutes 30 minutes	0 3 na 0 3 na 0 3 na 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0		na na na		Steady Flow Surges Down to Nothing No Flow Gas Gas and Water Water			
If bradenhead flowed water, check all of the descriptions that apply below:								
Clear	Fresh 🗖	Salty		Sulfur [	Blac	k 🗖		
5 Minute Shut-in Bradenhead 0 Intermediate na								
REMARKS:  By:				·	/itness:			
Kenny Brud	ce operator							
	(Position)	•						