Submit by Email
-----------------

Print Form

## NEW MEXICO ENERGY, MINERALS AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION

AZTEC DISTRICT OFFICE 1000 RIO BRAZOS ROAD AZTEC, NM 87410 (505 334-6178 FAX (505) 334-6170 http://www.emnrd.state.nm.us/ocd/

## **BRADENHEAD TEST**

Date of Test 05/25/09			Operator	perator Red Willow Production			API#	30-045-23838
Property Name	construction	d 22-2 e and Number)	Locatio	on: Unit B	Section	n 22 Township 2	on Ran	ge 12w
Well Status: Sh Pressures: OPEN I	Tubing 9	ducing pro	mediate na	Casing E		Bradenhead 0		CVD JUL 7'09 IIL CONS. DIV. DIST. 3 
			s INT Ionitor	Intermediate Blowdown	,	Brad	lenhead Intermediate	
10 minutes	0 3 0 3 0 3	na na na		na [na ]		Steady Flo Surge Down to Nothir No Flo Ga Gas and Wat Wat	es	
Clear   5 Minute Shu	Fre	ter, check a sh ☐ denhead 0	Salty		Sulfur		ack [	נ
REMARKS:  By:  Kenny Bruce	e operator (Position	1)				Witness:		