

NEW MEXICO ENERGY, MINERALS AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505 334-6178 FAX (505) 334-6170
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST

RCVD JUL 7 '09
OIL CONS. DIV.
DIST. 3

Date of Test 05/7/09

Operator

Running Horse
~~Kenny Bruce~~

API #

30-045-28073

Property Name cowsaround 21-1

Location:

Unit a

Section 21

Township 26n

Range 12w

(Well Name and Number)

Well Status: Shut-in or Producing

producing

Pressures:

Tubing 8

Intermediate na

Casing 3

Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Bradenhead PSIs

Intermediate

Bradenhead Intermediate

Time	BH Blowdown	Casing Monitor	INT Monitor	Intermediate Blowdown	Casing Monitor		
5 minutes	0	3	na	na		Steady Flow	<input type="checkbox"/>
10 minutes	0	3	na	na		Surges	<input type="checkbox"/>
15 minutes	0	3	na	na		Down to Nothing	<input type="checkbox"/>
20 minutes						No Flow	<input checked="" type="checkbox"/>
25 minutes						Gas	<input type="checkbox"/>
30 minutes						Gas and Water	<input type="checkbox"/>
5 minute SI	0			na		Water	<input type="checkbox"/>

If bradenhead flowed water, check all of the descriptions that apply below:

Clear ☐Fresh ☐Salty ☐Sulfur ☐Black ☐

5 Minute Shut-in

Bradenhead

0

Intermediate

na

REMARKS:

By:

Kenny Bruce operator

(Position)

Witness: