



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3rdistrict.htm](http://emnrd.state.nm.us/ocd/District%20III/3rdistrict.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 6/9/09 Operator Benson Martin Green API # 30-045-21847
Property Name La Plata Well No. 2 Location: Unit H Section 30 Township 32N Range 13W
Well Status (Shut-In or Producing) Initial PSI: Tubing 6.7 Intermediate N/A Casing 15.3 Bradenhead 16.8

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE						FLOW CHARACTERISTICS	
	Bradenhead			INTERM			BRADENHEAD	INTERMEDIATE
	BH	Int	Csg	Int	Csg			
TIME								
5 min	<u>2.1</u>		<u>14.6</u>				Steady Flow <u>He. 8</u> ✓	
10 min	<u>1</u>		<u>14</u>				Surges	
15 min	<u>.9</u>		<u>14</u>				Down to Nothing	
20 min	<u>.6</u>		<u>14</u>				Nothing	
25 min	<u>.6</u>		<u>14</u>				Gas ✓	
30 min	<u>.6</u>		<u>14</u>				Gas & Water	
							Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 10 INTERMEDIATE N/A

REMARKS:

A slight steady flow

By Jim Barnes

Witness _____

Lease Operator
(Position)

E-mail address _____

