

NEW MEXICO ENERGY, MINERALS  
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division  
Aztec District Office  
1000 Rio Brazos Road  
Aztec, NM 87410  
(505)334-6178 FAX:(505)334-6170

<http://emnr.state.nm.us/ocd/District/III/3district.htm>

**BRADENHEAD TEST REPORT**  
(Submit 1 copy to above address)

Date of Test 5-27-09 Operator Dugan Production Corp. API # 30-045-25904  
Property Name JULY JUBILEE Well No 3 Location: Unit L Section 29 Township 24N Range 9W  
Well Status (Shut-In or Producing) Initial PSI: Tubing 0 Intermediate \_\_\_\_\_ Casing 0 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

FLOW CHARACTERISTICS

TIME	Bradenhead			Interim				FLOW CHARACTERISTICS	
	BH	Int	Csg	Int	Csg			BRADENHEAD	INTERMEDIATE
5 minutes	0		0				Steady Flow		
10 minutes	0		0				Surges		
15 minutes	0		0				Down to Nothing		
20 minutes							Nothing	✓	
25 minutes							Gas		
30 minutes							Gas & Water		
							Water		

**If bradenhead flowed water, check all of the descriptions that apply below:**

CLEAR \_\_\_\_\_ FRESH \_\_\_\_\_ SALTY \_\_\_\_\_ SULFUR \_\_\_\_\_ BLACK \_\_\_\_\_

**5 MINUTE SHUT-IN** BRADENHEAD 0 INTERMEDIATE \_\_\_\_\_

REMARKS:

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

By \_\_\_\_\_ Witness \_\_\_\_\_

\_\_\_\_\_  
Switcher  
(Position)

