NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

Oil Conservation Division
Aztec District Office
1000 Rio Brazos Road
Aztec, NM 87410
(505)334-6178 FAX:(505)334-6170

http://emnrd.state.nm.us/ocd/District III/3distric.htm

BRADENHEAD TEST REPORT

(Submit 1 copy to above address)

Date of Test	5:27.09 Operator	Dugan Production Corp.	API# <u>30-045-25920</u>
Property Name	FABULOUS FEB	_ Well No1 Location: U	Unit D Section31_ Township24N_ Range9W
Well Status(Shut	t-In or Producing) Initial PSI:	Tubing 20_ Intermediate	e Casing A Bradenhead
TIME	ENHEAD AND INTERME PRESSURE Brädenhead Interm BH Int Csg Int Csg	7 -	INDIVIDUALLY FOR 15 MINUTES EACH FLOW CHARACTERISTICS BRADENHEAD INTERMEDIATE
5 mintues 10 minutes 15 minutes	0 21	Steady Flow Surges Down to Nothing	
20 minutes		Nothing	
30 minutės		Gas & Water	
	· · · · · · · · · · · · · · · · · · ·	Water	
If bradenhead flowed water, check all of the descriptions that apply below: CLEAR FRESH SALTY SULFUR BLACK			
5 MINUTE SH REMARKS:			NTERMEDIATE BLACK NTERMEDIATE OR RECEIVED OIL CONS. DIV. DIST. 3
		0	5.0E 65 82 15 05 62 12/00 CC 1
By -	Switcher (Position)	<u>teroil</u> v	Witness