

NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division
Aztec District Office
1000 Rio Brazos Road
Aztec, NM 87410
(505)334-6178 FAX (505)334-6170

<http://emnr.state.nm.us/ocd/District/III/3distinc.htm>

BRADENHEAD TEST REPORT

(Submit 1 copy to above address)

Date of Test 5-21-09 Operator FOUR CORNERS EXP API # 30-045-26730
Property Name SO BISTI FEDERAL Well No 29-1 Location: Unit A Section 36 Township 27N Range 13W
Well Status(Shut-In or Producing) Initial PSI: Tubing 40 Intermediate N/A Casing 40 Bradenhead 45

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

TIME	Bradenhead			Interm		
	BH	Int	Csg	Int	Csg	
5 minutes	10		40			
10 minutes	10		40			
15 minutes	0		40			
20 minutes	0		40			
25 minutes	0		40			
30 minutes	0		40			

Steady Flow

Surges

Down to Nothing

Nothing

Gas

Gas & Water

Water

FLOW CHARACTERISTICS

BRADENHEAD	INTERMEDIATE
X	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN

BRADENHEAD

15

INTERMEDIATE

REMARKS:

Steady flow from Bradenhead, but, there is no-
communication between bradenhead and casing.

By

Travis Breton #38
Switcher
(Position)

Witness

