## NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

Oil Conservation Division
Aztec District Office
1000 Rio Brazos Road
Aztec, NM 87410
(505)334-6178 FAX:(505)334-6170

http://emnrd.state.nm.us/ocd/District III/3distric.htm

## **BRADENHEAD TEST REPORT**

(Submit 1 copy to above address)

Date of Test	<u>05-18-09</u> Operator	Dugan Prod	luction Corp.	AI	PI# <u>30-04</u>	5-28372	sakan s	/
Property Name	CHACO PLANT	_Well No9	0 Location	Unit	B Section	17 Township	26N Range	12W
Well Status(Sh	out-In or Producing) Initial PSI:	Tubing 4	Intermed	iate	Casing	4	_Bradenhead	Ø
OPEN BRA  TIME 5 minutes 10 minutes 15 minutes 20 minutes 25 minutes 30 minutes	DENHEAD AND INTERME PRESSURE Bradenhead Interm BH Int Csg Int Csg O 4 O 4 O 9 O 9 O 9 O 9	Stead Surge Down Nothir Gas Gas 8	TMOSPHERI by Flow to Nothing ng k Water	FI BI	UALLY FOF	R 15 MINUTES TERISTICS INTERME	EACH	
<b>5 MINUTÉ</b> : RÉMARKS:	CLEAR				ULFUR			
Ву	Switcher (Position)	chuga	#-26	Witness		123486 0000	ECEIVED  2000  CONS. DIV. DIST, 3	1181920212223