

NEW MEXICO ENERGY, MINERALS  
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division  
Aztec District Office  
1000 Rio Brazos Road  
Aztec, NM 87410  
(505)334-6178 FAX:(505)334-6170

[http://emnr.state.nm.us/ocd/District III/3distnc.htm](http://emnr.state.nm.us/ocd/District%20III/3distnc.htm)

**BRADENHEAD TEST REPORT**

(Submit 1 copy to above address)

Date of Test 5-27-9 Operator Dugan Production Corp. API # 30-045-26435  
Property Name BRONZE MEDAL Well No 1 Location: Unit D Section 3 Township 23N Range 10W  
Well Status(Shut-In or Producing) Initial PSI: Tubing 60 Intermediate NA Casing 50 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

FLOW CHARACTERISTICS

TIME	Bradenhead			Interm				FLOW CHARACTERISTICS	
	BH	Int	Csg	Int	Csg			BRADENHEAD	INTERMEDIATE
5 minutes	0		50				Steady Flow		
10 minutes	0		50				Surges		
15 minutes	0		50				Down to Nothing	X	
20 minutes	0		50				Nothing		
25 minutes	0		50				Gas		
30 minutes	0		50				Gas & Water		
							Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR \_\_\_\_\_ FRESH \_\_\_\_\_ SALTY \_\_\_\_\_ SULFUR \_\_\_\_\_ BLACK \_\_\_\_\_

5 MINUTE SHUT-IN

BRADENHEAD 0

INTERMEDIATE \_\_\_\_\_

REMARKS:

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

By Mike Suen +53  
Switcher  
(Position)

Witness \_\_\_\_\_

