NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

Oil Conservation Division
Aztec District Office
1000 Rio Brazos Road
Aztec, NM 87410
(505)334-6178 FAX:(505)334-6170

http://emnrd.state.nm.us/ocd/District III/3distric.htm

BRADENHEAD TEST REPORT

(Submit 1 copy to above address)

Date of Test	5-21-1 Operator		Dugan Production Corp.			API #	30-045-26436			
Property Name	MARA	THON	_Well No	1	_Location: Unit	A	_Section .	4Township	23N_Rang	e <u>10W</u>
Well Status(Shut-In or Producing) Initial PSI:		Tubing_	<u>H5</u>	Intermediate_		_Casing _	50	Bradenh <u>ead</u>	0	
OPÉN BRAI	DENHEAD AN	SURE	EDIATE 7	ГО АТМО	OSPHERE INC				EACH	
	Bradenhead Interm				FLOW CHARACTERISTICS					
TIME	BH Int Csg	Int Csg	Т			BRAD	ENHEAD	INTERM	EDIATE	
5 mintues	0 30		4	Steady Flo	w					
10 minutes	0 50		_	Surges				<u> </u>		
15 minutes	0 50			Down to No	othing	X				
20 minutes	0 50			Nothing				1		
25 minutes	0 50	 	7	Gas				<u> </u>		
	0 50	1	_					<u> </u>		
30 minutes		Щ	_	Gas & Wat	er			<u> </u>	<u> </u>	
				Water						
If bradenh	iead flowed v	vater. che	ck all o	f the de	scriptions t	nat appl	v below	<i>I</i> :		
<u></u>								-		
	CLEAF	₹	FRESH		SALTY	SULFU	JR	BLACK	211121370	
5 MINUTE S	SHUT-IN							\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	RECEIVE	Ser is
REMARKS			•		_			345	MECEIVE	5/920 D
	<u> </u>						· · · ·	/7/0	IL CONS. DIV. DIST	[3 \lambda \frac{27}{2}
			- 					Co		No colo
			-					·	0677.00	
Ву	mik	e Srea	100	3	Witn	ess		_	<u>.</u>	
	_	Switcher							<u> </u>	
		(Position)	·		·					