

NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division
Aztec District Office
1000 Rio Brazos Road
Aztec, NM 87410
(505)334-6178 FAX:(505)334-6170

[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(Submit 1 copy to above address)

Date of Test 5-27-9 Operator Dugan Production Corp. API # 30-045-26927
Property Name MARATHON Well No 2 Location. Unit G Section 4 Township 23N Range 10W
Well Status (Shut-In or Producing) Initial PSI: Tubing 0 Intermediate 0 Casing 0 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

FLOW CHARACTERISTICS

TIME	Bradenhead			Interm				FLOW CHARACTERISTICS	
	BH	Int	Csg	Int	Csg			BRADENHEAD	INTERMEDIATE
5 minutes	0		0				Steady Flow		
10 minutes	0		0				Surges		
15 minutes	0		0				Down to Nothing	X	
20 minutes	0		0				Nothing	X	
25 minutes	0		0				Gas		
30 minutes	0		0				Gas & Water		
							Water		


If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN BRADENHEAD 0 INTERMEDIATE _____

REMARKS:

pump hole problems



By mike Sural PS3 Witness _____
Switcher
(Position)