NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

Oil Conservation Division
Aztec District Office
1000 Rio Brazos Road
Aztec, NM 87410
(505)334-6178 FAX (505)334-6170

http://emnrd.state.nm.us/ocd/District III/3distric.htm

BRADENHEAD TEST REPORT

(Submit 1 copy to above address)

Date of Test 5-21-09 Operator	Dugan Production Corp.	API# <u>30-045-32</u>	2086
Property Name MESA SWD	Well No 4 Location: U	nit I Section 1	6 Township 24N Range 8W
Well Status(Shut-In or Producing) Initial PS	SI: Tubing Intermediate	Casing /	Bradenhead Ø
OPEN BRADENHEAD AND INTERI	MEDIATE TO ATMOSPHERE II	NDIVIDUALLY FOR 15	MINUTES EACH
PRESSURE			
Bradenhead Interm		FLOW CHARACTER	RISTICS
TIMÉ BH Int Csg Int Cs	g	BRADENHEAD	INTERMEDIATE
5 mintues / '/	Steady Flow		
10 minutes	Surges		<u> </u>
15 minutes	Down to Nothing	Han	
20 minutes	Nothing		·
25 minutes	Gas		
30 minutes	Gas & Water		RCVD JUL 13 '09
·	Water		OIL CONS. DIV.
If bradenhead flowed water, ch	neck all of the descriptions	that apply below:	DIST. 3
CLEAŘ	FRESHSALTY	SULFURBLA	ACK
5 MINUTE SHUT-IN BRADENI	HEAD <u>(</u>	ITERMEDIATE	
RÈMARKS:			
B. Head pushed To	1 B		
	<u> </u>	· · · · · · · · · · · · · · · · · · ·	- /
ву	, v	litness	····

(Position)