

NEW MEXICO ENERGY, MINERALS  
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division  
Aztec District Office  
1000 Rio Brazos Road  
Aztec, NM 87410  
(505)334-6178 FAX:(505)334-6170

<http://emnr.state.nm.us/ocd/District/III/3district.htm>

**BRADENHEAD TEST REPORT**

(Submit 1 copy to above address)

Date of Test 5-27-09 Operator Dugan Production Corp. API # 30-045-32272  
Property Name CHACO Well No 5 Location: Unit P Section 6 Township 24N Range 8W  
Well Status (Shut-In or Producing) Initial PSI: Tubing 15 Intermediate - Casing 25 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

TIME	Bradenhead			Interm		
	BH	Int	Csg	Int	Csg	
5 minutes	<u>0</u>		<u>25</u>			
10 minutes	<u>0</u>		<u>25</u>			
15 minutes	<u>0</u>		<u>25</u>			
20 minutes						
25 minutes						
30 minutes						

Steady Flow

Surges

Down to Nothing

Nothing

Gas

Gas & Water

Water

FLOW CHARACTERISTICS

BRADENHEAD INTERMEDIATE

BRADENHEAD	INTERMEDIATE
<u>DTN</u>	

RCVD JUL 13 '09

OIL CONS. DIV.

If bradenhead flowed water, check all of the descriptions that apply below:

DIST. 3

CLEAR \_\_\_\_\_ FRESH \_\_\_\_\_ SALTY \_\_\_\_\_ SULFUR \_\_\_\_\_ BLACK \_\_\_\_\_

5 MINUTE SHUT-IN

BRADENHEAD

0

INTERMEDIATE

REMARKS:

B-Head Pressed To 0

By [Signature] Witness \_\_\_\_\_

Switcher

(Position)