## NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

Oil Conservation Division
Aztec District Office
1000 Rio Brazos Road
Aztec, NM 87410
(505)334-6178 FAX:(505)334-6170

http://emnrd.state.nm.us/ocd/District III/3distric.htm

## **BRADENHEAD TEST REPORT**

(Submit 1 copy to above address)

Date of Test	<u>5-27-09</u> Operator	Dugan Production Corp.	API#	30-045-32273		
Property Name	CHACO	Well No 90 Location:	Unit <u>F</u>	_Section _	6 Township	24N Range 8W
Well Status(Sh	ut-In or Producing) Initial PSI:	Tubing 20 Intermedia	ite	Casing	03	Bradenhead
	ACT THE PROPERTY OF STREET					-
OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH						
	PRESSURE Bradenhead Interm		EI OW	CHABACT	TERISTICS	
TIME	BH Int Csg Int Csg			ENHEAD	INTERME	DIATE
5 mintues	W 23	Steady Flow				
10 minutes	1 23	Surges				
15 minutes		Down to Nothing	1771	··		<del></del>
	<i>D</i> 23	1 .	11/1/1/			<del></del> _
20 minutes		Nothing				
25 minutes		Gas				 ) JUL 13 '09
30 minutes		Gas & Water			*	
		Water	<u></u>	<u>,                                     </u>	AC LOSS	<u>come div.</u>
DIST. 3 If bradenhead flowed water, check all of the descriptions that apply below:						
	CLEAR	FRESHSALTY	SULFU	JR	BLACK	_
5 MINUTE SHUT-IN BRADENHEAD INTERMEDIATE						
REMARKS:						
B-Had Pilled To O						
						nne,
						·
					<u> </u>	
	1 - 8 1 Man -					
Ву	Switcher		Witness		· · · · · · · · · · · · · · · · · · ·	<del></del>

(Position)