Submit by	Email
-----------	-------

Print Form

NEW MEXICO ENERGY, MINERALS AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION

AZTEC DISTRICT OFFICE 1000 RIO BRAZOS ROAD AZTEC, NM 87410 (505 334-6178 FAX (505) 334-6170 http://www.emnrd.state.nm.us/ocd/

BRADENHEAD TEST

Date of Test	4/22/09	Operator	Kukui		АР	1# 30	-045-32431		
Property Name Angel Peak 1 #20\$ Location: Unit Section Township 27N Range 10W									
Well Status: Shut-in or Producing Packers									
Pressures:	Tubing 8 Int	ermediate	Casing	8 Bra	adenhead 0				
OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH									
Bradenhead PSIs Intermediate			liate		Dandanh				
<u>Time</u>	BH Casing Blowdown Monitor	INT Monitor	Intermediate Blowdown	Casing Monitor		bradenne	ead Intermediate		
5 minutes 10 minutes 15 minutes 20 minutes 25 minutes 30 minutes	0 8 0 8 0 8 0 8				Steady Flow Surges Down to Nothing No Flow Gas Gas and Water Water				
If bradenhe	ead flowed water, chec	k all of the de			<u>v:</u>] Black	173742526 2526	RECEIVED 2009 CONS. DIV DIST 3 COZ 61 81 LL 9 CHAN		
5 Minute St	h ut-in Bradenhead	0	Intermediate			732425	CONS. DIV DIST 3		
REMARKS:	re was noth	ng				ا دخير	.0561817781219		
By: leas	c Operator			W	Jitness:	forze	K		