



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3ddistrict.htm](http://emnrd.state.nm.us/ocd/District%20III/3ddistrict.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 4-15-09 Operator McElvain Oil & Gas Properties, Inc. API #30-045-08854

Property Name Southern Union Well No. 1B Location: Unit B Section 3 Township 29 Range 13

Well Status(Shut-In or **Producing**) Initial PSI: Tubing 215 Intermediate Casing 510 Bradenhead 10

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE					FLOW CHARACTERISTICS	
	Bradenhead			INTERM		BRADENHEAD	INTERMEDIATE
	BH	Int	Csg	Int	Csg		
TIME							
5 min	<u>0</u>		<u>510</u>			Steady Flow	
10 min	<u>0</u>		<u>510</u>			Surges	
15 min	<u>0</u>		<u>510</u>			Down to Nothing <u>xx-fumes</u>	
20 min						Nothing	
25 min						Gas <u>for 2 min. thru. 1"</u>	
30 min						Gas & Water	
						Water	


If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE

REMARKS:

 vulnerable area



By Randy J. Elledge

Witness

 Foreman
(Position)

E-mail address Relledge @wapitisvc.com