Submit 3 Copies To Appropriate District State of New Mexico Office Figure Minerals and Netural Recourage				Form C-103 June 19, 2008		
District I 1625 N. French Dr., Hobbs, NM 88240 District II 1301 W. Grand Ave., Artesia, NM 88210	OIL CONCEDUATION DIVICION		VISION 3	WELL API NO. 30-045-34137 5. Indicate Type of Lease		
District III	1220 South St. Francis Dr.				of Lease FEE	
1000 Rio Brazos Rd., Aztec, NM 87410 <u>District IV</u> 1220 S. St. Francis Dr., Santa Fe, NM	Santa Fe, NM 8/303			6. State Oil & Gas Lease No. E-292-9		
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)				7. Lease Name or Unit Agreement Name Northeast Blanco Unit		
1. Type of Well: Oil Well Gas Well Other				8. Well Number #47N		
2. Name of Operator				9. OGRID Number 06137		
Devon Energy Production Company, L.P.				10 P. L. Will A P. C P. L.		
3. Address of Operator PO Box 6459, Navajo Dam, NM 87419				Pool name or Wildcat: Basin Dakota Blanco Mesaverde		
4. Well Location	2015 C . 2	acrimit !	1 1000		WEDOW 1:	
Unit Letter K: 2015 feet from the SOUTH line and 1800 feet from the WEST line Section 32 Township 31-N Range 7-W NMPM San Juan County						
Section 32	Township 11. Elevation (Show w.			MPM San Jua	n County	
6379' GL						
12. Check	Appropriate Box to Ir	ndicate Natu	re of Notice, Re	eport or Other	Data	
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:						
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WOR						
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DR				ING OPNS.□	P AND A	
PULL OR ALTER CASING	MULTIPLE COMPL		ASING/CEMENT J			
DOWNHOLE COMMINGLE						
OTHER: Repair Tubing or	Packer Leak	a o	THER:		П	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date						
of starting any proposed we or recompletion.	ork). SEE RULE 1103. I	For Multiple C	ompletions: Attac	h wellbore diagra	am of proposed completion	
This MV/DK dual well failed its nkr	· leakage test on 7/28/09	Therefore De	evon plans to MI a	workover rig & '	TOH w/that & nkr After	
This MV/DK dual well failed its pkr leakage test on 7/28/09. Therefore, Devon plans to MI a workover rig & TOH w/tbg & pkr. After the tbg & pkr have been tested & the defective materials replaced, the tbg & pkr will be rerun and dual MV/DK production resumed. A pkr leakage test will be performed in the near future. RCUD JUL 28 '09						
				J.	IL CONS. DIV.	
					DIST. 3	
I hereby certify that the information	shove is true and comple	te to the hest o	f my knowledge ar	nd helief		
I hereby certify that the information above is true and complete to the best of my knowledge and belief.						
SIGNATURE MACLE	TIT TIT	LE_Petroleum	Engineer - Agent	DATE	7/27/09	
Type or print name Mike Pippin	E-ma	il address:	mike@pippinllc.c	com PHO	NE: <u>505-327-4573</u>	
For State Use Only Deputy Oil & Gas Inspector, The Control of the						
APPROVED BY: Lely G						
Conditions of Approval (if any):	TITI & Co.S.		District #		THUL 2 9 2009	

NOTIFY NMOCD AZTEC 24 HOURS PRIOR TO BEGINNING WORK.