Form 3 60-5 (August 2007)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

IDDY NOTICES AND DEPORTS ON WELLS

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an
abandoned well. Use form 3160-3 (APD) for such proposals.

FORM APPROVED OMB NO. 1004-0135 Expires: July 31, 2010

Expires:	July	31,
Lease Serial No.		
NMSF078091		

6. If Indian, Allottee or Tribe Name


	abandoned wen. Ose form 5100-5 (Ar b) for such proposals.				SHIP ROCK		
=	SUBMIT IN TRI	PLICATE - Other instruc	tions on reverse side.		7. If Unit or CA/Agre NMNM78448X	ement, Name and/or No	
	1. Type of Well ☐ Gas Well ☑ Other: INJECTION				8. Well Name and No WEST BISTI 125		
Name of Operator Contact: JOHN CALEXANDER DUGAN PRODUCTION CORPORATION DUGAN PRODUCTION CORPORATION					9. API Well No. 30-045-05682-00-S1		
_	3a. Address P. O. BOX 420 FARMINGTON, NM 8749904.	20	3b. Phone No. (include area code Ph: 505-325-1821	e)	10. Field and Pool, or BISTI	Exploratory	
	4. Location of WcII (Footage, Sec., T Sec 27 T26N R13W SWNE 21 36.46048 N Lat, 108.20367 W	163FNL 2031FEL)		11. County or Parish, SAN JUAN CO		
-	12. CHECK APPR	ROPRIATE BOX(ES) TO	O INDICATE NATURE OF 1	NOTICE, RE	PORT, OR OTHE	R DATA	
_	TYPE OF SUBMISSION	TYPE OF ACTION					
- ?	□ Notice of Intent Subsequent Report Final Abandonment Notice	☐ Acidize ☐ Alter Casing ☐ Casing Repair ☐ Change Plans ☐ Convert to Injection	Deepen Fracture Treat New Construction Plug and Abandon Plug Back	Reclama Recomp Tempora Water D	olete arily Abandon Disposal	☐ Water Shut-Off ☑ Well Integrity ☐ Other	
-	13. Describe Proposed or Completed Op- If the proposal is to deepen directions Attach the Bond under which the wor following completion of the involved testing has been completed. Final At- determined that the site is ready for finance.	ertical depths of all perti esequent reports shall be new interval, a Form 316	nent markers and zones. e filed within 30 days 60-4 shall be filed once				
	Pressure tested casing to 500 witnessed by Navajo EPA. The sundry will be submitted to rep	e pressure chart is attacl	hed. The test was conducted	st was I 7/29/2009. 7	A		
		,			nain alla	0A 1A0	

RCVD AUG 20 '09 OIL CONS. DIV. DIST. 3

NOTIFY NUMBER AZTEC PRIOR TO WELL REPAIR

1001111 10	THEIR THUR TO WELL REPAIR		
14. I hereby certify	that the foregoing is true and correct. Electronic Submission #73399 verified For DUGAN PRODUCTION CORPO Committed to AFMSS for processing by ST	PRÁTION, sent to the Farmingtón	
Name (Printed/T	(yped) JOHN C ALEXANDER	Title VICE-PRESIDENT	
Signature	(Electronic Submission)	Date 08/18/2009	•
	THIS SPACE FOR FEDERA	AL OR STATE OFFICE USE	
Approved By ACCEPTED		STEPHEN MASON Title ACTING FIELD MANAGER MINERALS Date 08/	/18/2 0
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.		Office Farmington	

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.



Send Email

From:

smason@blm.gov

To:

johncalexander@duganproduction.com

CC:

Subject:

Well WEST BISTI 125

Message:

The sundry for Mechanical or Casing Integrity Test you submitted has been accepted by the BLM. Your original EC transmission was assigned ID 73399. Please be sure to open and save all attachments to this message, since they contain important information

You are required to submit a procedure to either repair or plug by September

25, 2009.

Attachments:

EC73399.pdf

Approved By:

STEPHEN MASON

ACTING FIELD MANAGER MINERALS

Status:

Queued to Send 2009-08-18 14:34:17