

Form 3160-5
(November 1983)
(Formerly 9-331)

5 BLM

1 File

1 - WBU wios

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	5. LEASE DESIGNATION AND SERIAL NO. 14-20-603-735-A
2. NAME OF OPERATOR DUGAN PRODUCTION CORP.	6. IF INDIAN, ALLOTTEE OR TRIBE NAME Navajo Tribal
3. ADDRESS OF OPERATOR P.O. Box 420, Farmington, NM 87499	7. UNIT AGREEMENT NAME West Bisti Unit
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below) At surface 1980' FNL & 1980' FEL	8. FARM OR LEASE NAME West Bisti Unit
14. PERMIT NO. API#30-045- 05867-0000	9. WELL NO. 100
15. ELEVATIONS (Show whether OF, BT, CR, etc.)	10. FIELD AND POOL, OR WILDCAT Bisti Lower Gallup
	11. SEC., T., R., M., OR BLC. AND SUBV. OR AREA Sec. 13, T26N, R14W, NMPM
	12. COUNTY OR PARISH San Juan
	13. STATE NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PCCL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

Shut-in Extension

X

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work).*

Request 1 year extension of shut-in status of this well to continue evaluation of entire unit. Casing will be pressure tested to insure integrity. If casing fails pressure test, plans will be presented immediately to repair casing or plug and abandon.

THIS APPROVAL EXPIRES

DEC 31 1991

RECEIVED

JAN 28 1991

OIL CON. DIV
DIST. 3

I hereby certify that the foregoing is true and correct

SIGNED

John Alexander

TITLE Petroleum Engineer

DATE 12-12-90

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

NR0001

*See Instructions on Reverse Side