



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

MECHANICAL INTEGRITY TEST REPORT

(TA OR UIC)

Date of Test 9-8-09 Operator Action Oil Co Inc API # 30-0 45-09899

Property Name King Kong Well # 20 Location: Unit L Sec 4 Twn 30 Rge 19

Land Type:

State _____
Federal _____
Private _____
Indian Navajo

Well Type:

Water Injection _____
Salt Water Disposal /
Gas Injection _____
Producing Oil/Gas _____
Pressure observation _____

Temporarily Abandoned Well (Y/N) (N) TA Expires: _____

Casing Pres. _____ Tbg. SI Pres. _____ Max. Inj. Pres. _____
Bradenhead Pres. _____ Tbg. Inj. Pres. _____
Tubing Pres. _____
Int. Casing Pres. _____

RCVD SEP 8 '09
OIL CONS. DIV.
DIST. 3

Pressured annulus up to 480 psi. for 30 mins. Test passed/failed (N)

REMARKS:


This well has no bradenhead valve
stopped for 459
545 test
will call with packer

By [Signature]
(Operator Representative)

Witness [Signature]
(NMOCD)

Operator
(Position)

Revised 02-11-02



GRAPHIC CONTROLS CORPORATION
BUFFALO, NEW YORK

30-45-09899
CHART NO. MC MP-1500-150F
Action oil

METER

CHART PUT ON

TAKEN OFF

LOCATION

King Kong #20

REMARKS

Chart @ 1 Hr Rot.
JL Bjr

TEST ACCEPTABLE

9-8-89

PRINTED IN U.S.A.