OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410

(505) 334-6178 FAX: (505) 334-6170 http://emnrd.state.nm.us/ocd/DistrictIII/3distric htm

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test	of Test 8-17-69 Operator Western Minerals & Oil LLC					API #30-0 45-06248				
Property Name	Marron	Well No.	2 Location: Uni	<u>н</u>	Section	27	_Township	27N Range	08W	
Well Status (Shu	t-In or Producing)	Tubing 45	Intermediate		Casing	45	Bradenhead	-0		
OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH										
TIME	PRESSURES: INTERMEDIATE	CASING				B	RADENHEAD FLOWED	INTERMED! FLOV		
5 minutes		45	Steady Flow							
10 minutes		45_	Surges						-	
15 minutes		45	Down to Noth	ing		X				
20 minutes		45	Nothing							
25 minutes		45	Gas							
30 minutes		45	Gas & Water			-	***			
			Water							
Water If bradenhead flowed water, check all of the descriptions that apply below: CLEAR FRESH SALTY SULFUR BLACK SEP 2009										
Ву	boli Che		Vitness							
	(Positio									