OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505) 334-6178 FAX: (505) 334-6170
http://emnrd.state.nm/us/ocd/DistrictIII/3distric http://emnrd.state.nm/us/ocd/DistrictIII/3districtIII

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test	Operator M&G Drilling Company					API #30-0 45-2319			28		
Property Name	KRAUSE		Well No.	11A	_Location: Unit	<u>K</u>	Section	28	Township	Range	11W
Well Status (Shu	t-In or Producing)	Tubing	/3/	,	Intermediate	NA	_Casing	13/	Bradenhead	_0_	
	OPEN BRADENHEAD	AND IN	TERMED	ATE	то атмоѕрні	ERE INI	DIVIDUA	LLY FO	OR 15 MINUT	TES EACH	
TIME	PRESSURES: INTERMEDIATE	CA	SING		,			В	RADENHEAD FLOWED	INTERMED FLO	
5 minutes	NA	1-	3/		Steady Flow				Nothing	NA	
10 minutes		13	2/		Surges						
15 minutes	V		<u>'/</u>		Down to Nothin	g					
20 minutes					Nothing						
25 minutes					Gas						
30 minutes					Gas & Water						
					Water						
If bradenhead flo	owed water, check all of	the descrip	tions that a	pply be	elow:				/:	72 13 14 15 76 A RECEIVE SER 2008 OIL CONS. DIV. DI	777
CLEAR	FRESH	SA	ALTY		SULFUR	BL	ACK		60	BECEIVE	D 8
5 MINUTE SHU	T-IN BRADENHEAD	0	_ INT	ERMEI	DIATE				4567	SEP 2009	2122
REMARKS.									54	OIL CONS. DIV. DI	ST. 3 (3)
	BRADENHA	EAD_	Flou	NE,	o N	0 Tu/1	NG.			450505.8277	31.2x
Ву) USTINI			Witness	s						
****	(Position	1)									