

Schematic - Current

SAN JUAN 30-6 UNIT #401R

30-039-24366

Most Recent Job

Jobs	Primary Job Type	Secondary Job Type	Actual Start Date	End Date
Job Category WELL INTERVENTION	ROD & PUMP REPAIR		5/8/2008	5/12/2008

Well Config: - 30039243660000, 10/7/2009 7:26:33 AM

