

Schematic - Current

SAN JUAN 31-6 UNIT #205

30-039-24486

Most Recent Job

Jobs				
Job Category	Primary Job Type	Secondary Job Type	Actual Start Date	End Date
WELL INTERVENTION	Repair Downhole Failure	Packer Repair	4/12/2005	4/14/2005

Well Config: Vertical - Main Hole (0 - 1000.7), 10/7/2009 7:30:14 AM				
Schematic - Actual				

