



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

MECHANICAL INTEGRITY TEST REPORT

(TA OR UIC)

Date of Test 9/22/09 Operator Canoco API # 30-0 3924987

Property Name SAN JUAN 31-6 Well # 220 Location: Unit 5 Sec 33 Twn 31 Rge 6

Land Type:

State _____
Federal ☒ _____
Private _____
Indian _____

Well Type:

Water Injection _____
Salt Water Disposal _____
Gas Injection _____
Producing Oil/Gas _____
Pressure observation ☒ _____

Temporarily Abandoned Well ☒ (Y/N): _____ TA Expires: _____

Casing Pres. 0
Crownhead Pres. 0
Tubing Pres. 210
Int. Casing Pres. 6


Tbg. SI Pres. _____
Tbg. Inj. Pres. _____

Max. Inj. Pres. _____

Pressured annulus up to 620 psi. for 45 mins. Test passed/failed

REMARKS:

Backer set at 2948




By Darrell Savage
(Operator Representative)

Witness Derrick Vigil
(NMOCD)

Production Specialist
(Position)

Revised 02-11-02



7-22-09 **COPC**
GRAPHIC CONTROLS CORPORATION
BUFFALO, NEW YORK

COPC
DYNMOID

ST 31-6
#220
D5
C.O.P.

CSG TEST

BR 2221

RECEIVED
SEP 2009

OIL CONS. DIV. DIST. 3

TEST ACCEPTABLE

10-14-09